

COARSE FEED VALVES/ ROTARY AIR-LOCKS

TOTAL REFURBISHMENT OR NEW
MANUFACTURE



AREA OF CONCERN

The body & rotor wears due to heavy grinding abrasion. The gap between rotor blades and body increases making it difficult to control feed rate and smooth operation of rotor.

SOLUTION

Refurbish the body and rotor with added features like use of 'Hardox' or 'Enduraplates' or 'Cast-fused' liners for enhanced resistance to severe abrasion. The performance life is enhanced considerably.

APPLICATIONS

- Limes Stone
- Clinker,
- Slag or Coal

KEY PROCEDURE

- Removal of worn-out parts
- Fabrication of new parts
- Machining of rotor & body
- Fitting of new liners & assembly
- Balancing & finishing

SOME OF OUR END USERS

- ACC Ltd.
- OCL India Ltd.
- UltraTech Cement Ltd.
- Prism Cement Ltd.
- Nuvoco Vistas Corp. Ltd.
- Ambuja Cements Ltd.